

	UART DEBUG	DEBUG ON/OFF
	HDMI CEC/ARC	CEC/ARC ON/OFF
	Backlight	Adjust backlight
CI+ key usb upgrade	CI+ key usb upgrade	
SW information	SW information	
Non-linear	MODE	Feature Selection
	OSD 0	Curve adjustment
	OSD 25	
	OSD 50	
	OSD 75	
	OSD 100	
Channel table1	KTC factory Frequecy table set	
CI factory setting	No function	
Channel table2	KTC factory Frequecy table set	
Channel dvbt	KTC factory Frequecy table set	